

This Page Is Inserted by IFW Operations
and is not a part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

IMAGES ARE BEST AVAILABLE COPY.

**As rescanning documents *will not* correct images,
please do not report the images to the
Image Problem Mailbox.**

FIG. 1




FIG.2




FIG.3A




FIG.3B




FIG.3C




FIG.3D




FIG.4




FIG.5




FIG. 6

FIG. 7

FIG. 8

FIG.9




FIG.10




FIG.11




FIG.12




FIG.13




FIG.14

The diagram illustrates a table that maps the capacity of a transmission line (in bps) to its corresponding image quality level. Three arrows point to specific rows: arrow 31 points to the row for 1G, arrow 32 points to the row for 10M, and arrow 30 points to the row for 5.6K.

CAPACITY OF TRANSMISSION LINE (bps)	IMAGE QUALITY LEVEL
1G	LAYER 0
100M	LAYER 2
10M	LAYER 4
8M	LAYER 5
1M	LAYER 7
5.6K	LAYER 10

FIG.15




FIG.16




FIG.17




FIG.18




FIG.19




FIG.20




FIG.21



FIG.22A




FIG.22B



FIG.22C



FIG.22D



FIG.23

